

Product Change Notice – PCN_DIMM-MX6-PCIe-2_R2A

Rev	Date/Signature	Changes
1	11.07.2014/Sr	First Revision

1 Product affected

Product affected	Rev.	Replacement	Rev.
DIMM-MX6Q-PCIe-1-1G-2G	R1	DIMM-MX6Q-PCIe-2-1G-2G	R2A
DIMM-MX6Q-PCIe-1-1G-2G-ET	R1	DIMM-MX6Q-PCIe-2-1G-2G-ET	R2A
DIMM-MX6D-PCIe-1-1G-2G	R1	DIMM-MX6D-PCIe-2-1G-2G	R2A
DIMM-MX6D-PCIe-1-1G-2G-ET	R1	DIMM-MX6D-PCIe-2-1G-2G-ET	R2A
DIMM-MX6S-PCIe-1-1G-2G	R1	DIMM-MX6S-PCIe-2-1G-2G	R2A
DIMM-MX6S-PCIe-1-1G-2G-ET	R1	DIMM-MX6S-PCIe-2-1G-2G-ET	R2A

2 Change 1 – Production Improvements

2.1 Key Characteristics of the Change

Patches which was done manually are included into the PCB design.

2.2 Description of Change to the Customer

To improve production process and the product quality the patches of revision R1B are now included into the PCB design.

2.3 Customer Impact of Change and Recommended Action

No actions necessary.